

Thriftwood Scout Campsite Risk Assessment for:- Inflatabull. Completed by Colin Tilbrook 25/6/08 Review Date 25/6/2012

Hazard	Risk	Risk Control	Action recommended	Review/comments
Impact with floor	High	<ul style="list-style-type: none"> Crash matting at entrance Securely fastened door Trained staff 	<ul style="list-style-type: none"> Investigate additional 'pillow' to be sewn into unit 	Pillow not necessary
Impact with tethering devise	High	<ul style="list-style-type: none"> Cover with protective material 		No accidents. Not necessary to cover
Injury by contact with electrical blower		<ul style="list-style-type: none"> Blower kept away from inflatable Electrical system to have correct safety devise Electrical testing (see log) 	<ul style="list-style-type: none"> PAT blower annually 	
Impact with another user		<ul style="list-style-type: none"> Operate to manufacturers guidelines (4) Similar age group bookings 	<ul style="list-style-type: none"> Staff training (see log) Add to instructions 	
Weather	Medium	<ul style="list-style-type: none"> Check weather reports Do not use in wet weather Trained staff 		
Equipment failure	Medium	<ul style="list-style-type: none"> Regular inspections of equipment (see log) 	<ul style="list-style-type: none"> Inspection to be carried out by PIPA registered inspector 	
Manual Handling	High	<ul style="list-style-type: none"> MH procedures followed Trained Staff 	<ul style="list-style-type: none"> Regular Staff Training (see Log) 	
See Site Procedures for action.				

Review Date	Reviewed By	Recommendations
1/7/2010	Colin Tilbrook	Complete staff training for 2010 season
1/4/2011	C Tilbrook	Summer 2011 Training required as is inspection in june when unit 12mths old