

Thriftwood Scout Campsite Risk Assessment: **Buildings.**

Completed by Colin Tilbrook.

Date 1/5/2023

Next Review Date 1/5/2024

| Hazard | Who might be harmed | Existing controls | Severity 1-10 | Likelihood 1-10 | Rating (SxL) | Further Actions Required |
|--|---------------------|---|---------------|-----------------|--------------|--------------------------|
| Fire | All | Fire Risk assessment. Full Detection system regularly checked and serviced | 10 | 2 | 20 | Adequately controlled |
| Electrical Fault | All | All portable appliances checked annually. Building checked 5yearly | 10 | 2 | 20 | Adequately controlled |
| Child Protection | All | Accommodation – sole use Access to accommodation restricted Keep windows shut at night Check students are in rooms at ‘lights out’ | 5 | 1 | 6 | Adequately controlled |
| Room Hazards | All | Rooms checked before arrival Hot water temperature is limited. Boilers annually checked and serviced Check bunk beds | 5 | 2 | 10 | Adequately controlled |
| On-site Hazards | All | Road speed 5mph Open ponds and lakes Slippery & Uneven woodland floor | 2 | 2 | 4 | Adequately controlled |
| Getting Lost | All | Maps available from reception, plus 5+ on site. Site perimeter secured. CCTV on site | 2 | 6 | 12 | Adequately controlled |
| Legionella | All | Water systems kept above 65 degrees. Taps and showers flushed regularly on cleaning. | 9 | 2 | 18 | Adequately Controlled |
| See Site Procedures for action. | | | | | | |

| Rating | 81-100 | 61-80 | 41-60 | 21-40 | 11-20 | 0-10 |
|--------|------------------|----------------------|---------------------------|-----------------------|-----------------------|--------------|
| Action | Immediate Action | Action within 1 week | Not adequately controlled | Further Investigation | Adequately Controlled | Trivial Risk |